





| Aseptik-/Hygiene-Flanschverbindung DIN 11853-2 + DIN 11864-2 | | | | | | | Art.Nr. | EUR | Art.Nr. | EUR |
|--|---------------|----------|----------|----------|----------|----------|---------|--------|------------------------|----------------|
| Bundflansch ISO, DIN 11853-2  | DN | A | B | C | D | E | | | AISI316L-1.4404 | |
| | 13,5 | 54 | 10,3 | 13,5 | 40 | 4xM8x30 | | | 472829 | Anfrage |
| | 17,2 | 59 | 14 | 17,2 | 40 | 4xM8x30 | | | 472830 | Anfrage |
| | 21,3 | 62 | 18,1 | 21,3 | 24 | 4xM8x30 | | | 472831 | 33,40 |
| | 26,9 | 69 | 23,7 | 26,9 | 24 | 4xM8x30 | | | 472832 | 35,10 |
| | 33,7 | 74 | 29,7 | 33,7 | 24 | 4xM8x30 | | | 472833 | 37,50 |
| | 42,4 | 82 | 38,4 | 42,4 | 24 | 4xM8x30 | | | 472834 | 41,30 |
| | 48,3 | 88 | 44,3 | 48,3 | 24 | 4xM8x30 | | | 472835 | 43,60 |
| | 60,3 | 103 | 56,3 | 60,3 | 24 | 4xM8x30 | | | 472836 | 55,90 |
| | 76,1 | 125 | 72,1 | 76,1 | 24 | 8xM10x35 | | | 472837 | 68,10 |
| | 88,9 | 137 | 84,3 | 88,9 | 26 | 8xM10x35 | | | 472838 | 77,80 |
| 114,3 | 168 | 109,7 | 114,3 | 26 | 8xM10x40 | | | 472839 | 99,80 | |
| Sechskantschraube DIN 933  | DN | A | B | C | | | | | A2 - 70 | |
| | M8x30 | M 8 | 30 | 13 | | | | | 554733 | 0,50 |
| | M8x35 | M 8 | 35 | 13 | | | | | 554734 | 0,60 |
| | M10x35 | M 10 | 35 | 17 | | | | | 554735 | 0,90 |
| | M10x40 | M 10 | 40 | 17 | | | | | 554736 | 0,85 |
| | M12x50 | M 12 | 50 | 19 | | | | | 554738 | 1,55 |
| Sechskantmutter DIN 934  | DN | A | B | C | | | | | A2 - 70 | |
| | M8 | M 8 | 6,5 | 13 | | | | | 554833 | 0,20 |
| | M10 | M 10 | 8 | 17 | | | | | 554835 | 0,30 |
| | M12 | M 12 | 10 | 19 | | | | | 554838 | 0,35 |
| Unterlegscheibe DIN 125  | DN | A | B | C | | | | | A2 | |
| | 8 | 8,4 | 16 | 1,6 | | | | | 554933 | 0,10 |
| | 10 | 10,5 | 20 | 2 | | | | | 554935 | 0,10 |
| | 12 | 13 | 24 | 2,5 | | | | | 554938 | 0,20 |